

操作説明 アセンブリー一括STEPファイル出力

・操作手順

The image shows four sequential screenshots of a software interface for batch STEP file output from assembly files. Each screenshot is titled "アセンブリー一括STEPファイル出力".

- Screenshot 1:** The "変換元フォルダパス" (Source Folder Path) field is set to "c:\test". A red box highlights the text, and a red arrow points to it with the number 1.
- Screenshot 2:** The "リスト表示" (List Display) button is highlighted with a red box and a red arrow, with the number 2.
- Screenshot 3:** The file selection list shows "sample01.asm" and "sample02.asm". "sample01.asm" is highlighted in blue, and a red box highlights it with a red arrow, with the number 3.
- Screenshot 4:** The "出力先フォルダパス" (Output Folder Path) field is set to "c:\test\step". A red box highlights the text, and a red arrow points to it with the number 4.
- Screenshot 5:** The "実行" (Execute) button is highlighted with a red box and a red arrow, with the number 5.

- ① “変換元フォルダパス”に変換するアセンブリ(asmファイル)のフォルダパスを入力します。
- ② “リスト表示”をクリック。
- ③ “ファイル選択”に表示されたアセンブリを選択します。(+Shift,+Ctrlで複数選択可)
- ④ “出力先フォルダパス”にSTEPファイル出力をするパスを入力します。
- ⑤ ”実行”をクリック。(④で設定したパスにSTEPファイルが出力されます。)

※出力後のファイル名は「yyyymmdd_元のファイル名.stp」になります。

※実行時にSTEPファイルと同時にLogファイルも出力されます。